

5m.7.30.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME

Stl. Sw. Se. M/V. "CONCH."

Report

Gls.

No. *51965*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report. 24/6/92.)

Nature of Survey _____

1st Entry.

When due _____

✠ 100 A.I. (Steel) Carrying Petroleum in bulk.

1 D^c (Stl) 2nd D^c (Stl) Clear of Cargo tanks.

Longitudinal framing at bottom and at deck.

Cell D.B. u F 71 282t, D.T. f 32' 394t, F.P.T. 239t, A.P.T. 93t.

F.K. 14 B.H. Lloyd's A & C.P.

P 107', B 34', F 42'.

machy aft.

RETAINED

© 2019

Lloyd's Register
Foundation

W372-0092