

COPY.

of LEITH.

2nd December, 1939.

s.s. "CROWN ARUN" ex "HANNAH BOGE".

THIS IS CERTIFY that this vessel has been surveyed by the Surveyors to Lloyd's Register of Shipping, Leith, for the purpose of assigning a freeboard. The necessary particulars have been obtained and forwarded to the Committee, and the Freeboards as given below, assigned by the Committee to this ship, have been correctly marked on the ship's sides, in accordance with requirements.

Ordinary Cargo Ships.

Freeboard amidships from top of deck line, steel deck.			From centre of disc
Tropical Fresh Water	....	- ft. 7 $\frac{3}{4}$ ins.	9 $\frac{1}{2}$ ins. above.
Fresh Water	....	1 ft. 0 $\frac{1}{4}$ ins.	5 ins. above.
Tropical	....	1 ft. 0 $\frac{3}{4}$ ins.	4 $\frac{1}{2}$ ins. above.
Summer	....	1 ft. 5 $\frac{1}{4}$ ins.	
Winter	....	1 ft. 9 $\frac{3}{4}$ ins.	4 $\frac{1}{2}$ ins. below.
Winter North Atlantic	....	1 ft. 11 $\frac{3}{4}$ ins.	6 $\frac{1}{2}$ ins. below.

Ships Carrying Timber Deck Cargoes.

Freeboard amidships from top of deck line, steel deck.			From centre of disc.
Tropical Fresh Water Timber	-	ft. 3 $\frac{1}{2}$ ins.	13 $\frac{3}{4}$ ins. above.
Fresh Water Timber	-	ft. 8 $\frac{1}{4}$ ins.	9 ins. above.
Tropical Timber	-	ft. 8 $\frac{1}{2}$ ins.	8 $\frac{3}{4}$ ins. above.
Summer Timber	1	ft. 1 $\frac{1}{4}$ ins.	4 ins. above.
Winter Timber	1	ft. 7 $\frac{1}{2}$ ins.	2 $\frac{1}{2}$ ins. below.
Winter North Atlantic Timber	1	ft. 11 $\frac{3}{4}$ ins.	6 $\frac{1}{2}$ ins. below.

*John Houston*  
SURVEYOR TO LLOYD'S REGISTER OF SHIPPING.



© 2019

Lloyd's Register  
Foundation

W378-0158