

REPORT ON ANNUAL LOAD LINE SURVEY.


Name of Ship S.S. Bouclair Official Number 165949 Port of Registry Glasgow
 Place of Survey South Shields Dates of Survey 22nd Dec. 1939 & 12th Jan. 1940 Date of last Load Line Survey 19 Sept 1938 (new)

PARTICULARS OF SURVEY.

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
HATCHWAYS, INCLUDING SMALL HATCHWAYS.			
1. Exposed on freeboard deck.			
Coamings, their stays and stiffeners ...	Good		
Beams ...	Good		
Fore and afters ...	Good		
*Covers ...	Good		
*Tarpaulins ... (State number per hatchway)	Good		
*Cleats and battens ...	Good		
Lashings and their fittings ...	Good		
Wedges ... (Is supply, including spares, adequate?)	Good		
2. Exposed on superstructure decks, including raised quarter decks.			
Coamings, their stays and stiffeners ...	Good		
Beams ...	Good		
Fore and afters ...	Good		
*Covers ...	Generally good	3 wood covers renewed	12. 1. 40.
*Tarpaulins ... (State number per hatchway)	Good (2)		
*Cleats and battens ...	Good		
Lashings and their fittings ...	Good		
Wedges ... (Is supply, including spares, adequate?)	Good & adequate.		
3. Within superstructures not intact or not protected by Class I closing appliances.			
Coamings ...	Good		
Beams ...	Good		
Fore and afters ...	Good		
Covers ...	Generally good	1 wood cover renewed	12. 1. 40.
Tarpaulins ... (State number per hatchway)	Good (1)		
Cleats and Battens ...	Good		
Wedges ... (Is supply, including spares, adequate?)	Good & adequate.		

RETAIN

RETAIN



*Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Board of Trade Circular 1687, paragraph 117 (i)).

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
VENTILATORS IN EXPOSED POSITIONS.			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections	good		
Closing arrangements	good		
5. To spaces below decks of superstructures which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections	good		
Closing arrangements	good		
AIR PIPES.			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements	generally good	3 plugs renewed	12.1.40
7. Within partially enclosed superstructures.			
Closing arrangements	good		
MACHINERY CASINGS.			
8. Casing Top.			
Fiddle openings, their covers and fastenings	generally good	5 hinges renewed	12.1.40
Skylights, their fastenings, covers and lashings	good		
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings	good		
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings	good		
11. Within partially enclosed superstructures.			
Doors and fastenings	good		
12. FLUSH BUNKER SCUTTLES and chain attachments			
13. COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings, covers	good		

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPERSTRUCTURE BULKHEADS.			
Forecastle	—		
Bridge, fore end... ..	—		
Bridge, after end	Good ✓		
Poop	—		
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures	—		
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves	Good ✓		
17. SIDE SCUTTLES AND DEADLIGHTS			
	Good ✓		
18. GUARD RAILS			
	Good ✓		
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways	None		
20. LIFELINES (fittings and material)			
	None	A sample for test + fee	all
21. FREEING PORTS			
Shutters	—		
Protection bars	—		
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances	—		
23. ITEMS NOT INCLUDED IN THE FOREGOING			
	—		
24. LOAD LINE MARKS			
	Varied ✓		

RETAIN

RETAIN



