

1m. 12.15.

F.E.

Received by Chief Ship Surveyor

16.9.16

Received from Chief Ship Surveyor

VESSEL'S NAME

Sheels "Faraday"

Rpt.

Incl

No. 29526.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

37.45

Depth "d"

12.25

Framing: Table No.

3 page

Description

Single angle as approved

Longitudinal No.

5093.

Proportions

Length

10.01

Depth

Deck Sheerstrake - 62 of an inch instead of 36 as req.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✱ 100A-1 (Steel) Steam Trawler, as recommended.

✱ 100A-1 (Steel) Steam Trawler,

1 DK.

BK 7½. 4BH. Cam. Q76 F20 Laver.

Date of Build 6.16.

16.9.16



© 2019

Lloyd's Register Foundation

W 38-0056

Spacing
BEAMS, Second Deck, Single Angle, Bulb
Angle Plate Tee Bulb or Channel

Tie Plates outside Hatchways
Deck Material & thickness