

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Single Sc. M.V. "DOSINIA"

Report

Grk. No. 20643

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey FIRST ENTRY When due _____

100A1 "Carrying petroleum in bulk"

1 Dk., 2nd Dk. clear of cargo tanks, "Longitudinal framing at bottom and at deck".

Cell.DBuE 69' 162t, DTr 25' 281t, PPT 143t, APT 94t.

FK, 17BH., Lloyd's A & CP.

P 90', B 42', F 69'

Machy. aft

O.L. 484'.

RETAIN

James
bol
27.10.38

This is a sister ship to the "Davila".



© 2021

Lloyd's Register
Foundation

W382-0066