

CONDITION OF CLASS.

NAME OF VESSEL.. "DAYDAWN" .....

Extract from freeboard verification of marking form received  
from the .....SUNDERLAND..... Surveyors dated the 8.1.40. ✓

Moulded depth	28	ft.	1	ins.	/
Corresponding draught	25	ft.	3 $\frac{1}{2}$	ins.	/
Moulded depth as shewn on draught sheet	28	ft.	1 $\frac{1}{2}$	ins.	/
Tropical freeboard	2	ft.	6 $\frac{1}{2}$	ins.	/
Summer "	3	ft.	0 $\frac{3}{4}$	ins.	/
Winter "	3	ft.	7	ins.	/
W.N.A. "	-	ft.	-	ins.	/
Fresh Water allowance			6 $\frac{3}{4}$	ins.	/

Marked from ~~wood~~/steel upper deck.

Checked by..... *mw* .....

Date....20.2.40.....

RETAIN



© 2021

Lloyd's Register  
Foundation

W382 - 0208