

W.S. 480

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

ESSEL'S NAME Sw.T.S. M.V. "O.A. KNUDSEN" Rpt. Yes No. 45152

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Transverse No. 96.75Depth "d" ✓Framing: Table No. ✓Description Bulk angle frames as approvedLongitudinal No. 45399

Proportions

Length

13.5

Depth =

Deck Sheerstrake as approved.old Rules**RETAIN**

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100A I. (Steel) "Carrying Petroleum in Bulk"

2 dks (Stl)

Cell D.B. E 52' 187t, D.T.f 47' 624t, F.P.T. 245t, APT 215t

F.K, 16 B.H (10 to upper dk, 6 to 2nd dk), pt Cem, Lloyds A.C.P.

P 94', B 33', F 40'. "machinery apt"



© 2019

Lloyd's Register

W0285-0059

8/11/25