

Rpt. 12.

Copy

FREEBOARD VERIFICATION FORM FOR STEAMERS.

(When received in London Office 16.4.18)

Port

Vessel's Name

Sunland

Official No.

142374

No. in Reg. Book

106 Suth

Port of Registry (For Foreign Vessels)

Iron or Steel

Steel

State whether Classed by Lloyd's Register

Yes

Name of Owners

Date of Verification

11 April 1918

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line 2 ft. 6½ ins.

From centre of disc to top of statutory deck line }
at awning or part-awning deck . . . } ft. ins.

Fresh water line above centre of disc . . . 6 ins.

Indian Summer line above centre of disc . . . 4½ ins.

Winter line below centre of disc . . . 4½ ins.

~~Winter North Atlantic line below centre of disc~~ . . . ins.

Distance between the top of statutory deck }
line on vessel's side and the intersec- } at main, spar or upper dk. 1¾ ins.
tion of the continuation of upper side of }
~~wood or~~ iron deck with the vessel's side } at awning or pt.-awning dk. ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

55

S. Henshall

Surveyor.

(To be filled up in London Office.)

Statement No. 25702

Date of Committee's Minute 26.3.18

Moulded Depth for record

24 ft. 6 ins.

Freeboards compared and found correct by

date

Is fee paid?

Form for Certificate


Instructions

date

Certificate written

Noted for posting

Compulsory freeboards a condition of classification.



© 2019

Lloyd's Register

Foundation
W 390-0102