

RETAIN

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl Se GRACEFIELD*

Rpt. *Awc*

No. *83138*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(\*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.)

*1st Langt*

Transverse No. *10853*

Depth "d" *24.42*

Framing: Table No. *✓*

Description *Bulbangle frames as*

Longitudinal No. *31621*

*approved*

Proportions Length *14.01 to upper dk*  
Depth = *10.88 to bridge dk.*

Deck Sheerstrake *as approved*

*Revised Rules.*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*\* 100A. 1. (steel)*

*1 Dk (stl).*

*Cell SB 344' 11935. FPT 835 APT 1955.*

*FK. 6 BH. 4 ft. Cam 9 ft. Asp*

*P36 B350' F32' Lloyd's A & CP.*

*WMA.*

*31. 8. 28.*



© 2020

Lloyd's Register

W398-0094