

FREEBOARD REPORT on the

S.S. "Hjalmar Blomberg"

The Surveyor should be informed it is
concluded the depth of hatches given
on his report is the depth at side but
he should report the depth at centre.

W.D.
3.9.20
GKM



© 2019

Lloyd's Register
Foundation
W 400 - 0119