

Received by Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

VESSEL'S NAME Island Queen Rpt. Leith No. 18619**The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Type of Engine Triple ExpansionIf Boilers fitted with forced draught noTail Shaft. If fitted with a continuous liner no

If fitted with an outside gland of } yes.
 approved type

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + Line 5. 34 06

Subject to the dynamo governors being placed in order
Plan 30.5.34

W401-0070

RETAIN



© 2019

Lloyd's Register
Foundation

RECEIVED BY BOTTLES AVAILABLE FOR CONNECTION