


S.S. "IRENE MARIA"



500x.

Inter-crystalline crack in
Port Boiler.



© 2019

Lloyd's Register
Foundation