

Surveyors along with First Matey and ...  
sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "DELIA" Report LIV. No. 81744

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.) - Extract from Sub-Committee's Report, 24/5/03.)

Nature of Survey

When due

See also endorsements dated the 26<sup>th</sup> inst.

100 A.1 (steel) "With freeboard"

1 Dk (steel). "Well Dk"

Cell DB a 56', uE 20' f 108' 312t. FPT 56t. APT 17t.

FK. 4 BH. Com. Lloyd's A.Y.C.P. PVB 186', F 34'

Date of Build 1914.

12, 20 LIV.

SS. LIV. N<sup>o</sup> 3-12, 20.

Subject to doublings  
being fitted at forward well,  
30 fathoms of chain cable  
of proper size & test &  
75 fathoms 3<sup>3</sup>/<sub>4</sub>" steel wire  
being supplied. A new  
port driving wheel being  
supplied to windlass, &  
the pillaring arrangements  
being placed in order at  
the first opportunity.



2020

27-1-21

Lloyd's Register  
Foundation

W 404-0144

0146