

14 SEP 1949

Rpt. C-11 (a).

Lloyd's Register of Shipping.

Vol. 1362

REPORT ON ANNUAL LOAD LINE SURVEY.

Name of Ship BRITKON. Official Number 139456 Port of Registry HULL
Place of Survey LIVERPOOL. Dates of Survey 8 & 9 SEPT 1949 Date of last Load Line Survey 28.8.48.


PARTICULARS OF SURVEY.

Items examined.	Condition in which found.	Repairs Necessary.	Date entered.	
HATCHWAYS, INCLUDING SMALL HATCHWAYS.				
1. Exposed on freeboard deck.				
Coamings, their stays and stiffeners	good	RETAIN		
Beams	good			
Fore and afters	✓			
*Covers	good			
*Tarpaulins (State number per hatchway)	good			
*Cleats and battens	good			
Lashings and their fittings	good			
Wedges (Is supply, including spares, adequate?)	good. yes.			
2. Exposed on superstructure decks, including raised quarter decks.				
Coamings, their stays and stiffeners	good			
Beams	good			
Fore and afters	✓			
*Covers (Steel cover to A.P.K.)	good			
*Tarpaulins (State number per hatchway)	good			
*Cleats and battens Toggle fasteners	good			
Lashings and their fittings	good			
Wedges (Is supply, including spares, adequate?)	good. yes.			
3. Within superstructures not intact or not protected by Class I closing appliances.				
Coamings	good	Renew 24 wood covers Renew 8 tarpaulins Missing battens made good.	9.9.49	
Beams	good			
Fore and afters	✓			
Covers	good except			
Tarpaulins (State number per hatchway)	good except		9.9.49	
Cleats and Battens	good except		9.9.49	
Wedges (Is supply, including spares, adequate?)	good. yes.			
VENTILATORS IN EXPOSED POSITIONS.				
4. To spaces below freeboard deck.				
Coamings, their supports and deck connections	good	RETAIN		
Closing arrangements	good			
5. To spaces below decks of superstructure which are intact or closed by Class I appliances.				
Coamings, their supports and deck connections	✓			
Closing arrangements	✓			
AIR PIPES.				
6. Exposed on freeboard and superstructure decks.				
Closing arrangements	good			
7. Within partially enclosed superstructures.				
Closing arrangements	✓			
MACHINERY CASINGS.				
8. Casing Top.				
Fiddle openings, their covers and fastenings	good	RETAIN		
Skylights, their fastenings, covers and lashings	good			
9. Exposed on freeboard and raised quarter decks.				
Doors and fastenings	✓			
10. Exposed on superstructure decks other than raised quarter decks.				
Doors and fastenings	good			
11. Within partially enclosed superstructures.				
Doors and fastenings	good			
12. FLUSH BUNKER SCUTTLES and chain attachments				
	✓			
13. COMPANIONWAYS, including deckhouses enclosing ladderways.				
Doors, fastenings, covers	good.			

* Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Board of Trade Circular 1687, paragraph 117 (i)).

Rpt. C-11 (a) 5m.11.45.

W409-0129



© 2019

Lloyd's Register
Foundation

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPER-STRUCTURE BULKHEADS.			
Forecastle ...	good		
Bridge, fore end ...	good		
Bridge, after end ...	good		
Poop ...	good		
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures ...	✓		
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves ...	good		
17. SIDE SCUTTLES AND DEADLIGHTS ...	good except Renubber 1 deadlight		9.9.4
18. GUARD RAILS <i>& bulwarks.</i> ...	good		
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways ...	✓		
20. LIFELINES (fittings and material) ...	good		
21. FREEING PORTS.			
Shutters ...	good		
Protection bars ...	good except Straighten 1 bar.		9.9.4
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances ...	good		
23. ITEMS NOT INCLUDED IN THE FOREGOING.			
	good		
24. LOAD LINE MARKS ...			
	Verified.		

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Board of Trade Circular 16 and the requisite details of the survey have been entered herein.

Index Nos. of items examined. († Insert "all" in case of a complete survey.)	Signature of Surveyor.	Place.	Date.
all	Thos. J. Roberts	Liverpool	9 th September 1944

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor Thos. J. Roberts Place Liverpool Date 9th Sept 1944

Signature Thos. J. Roberts

Date 9th September 1944

Fees £10/-/-

Number of Visits 2

15 SEP 1944

Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11 should be reported on Form C 11 (contd.) and attached to the C 11 on the Ship, a copy being forwarded to the Freeboard Department.

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a certified of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.