

Port GLASGOW

7.20

to Chief Surveyors _____ Received from Chief Surveyors _____
SEL'S NAME Off Sc "GAZCON" Report G/S No. 52703

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey 1st Entry When due


✦ 100 A1 (Steel) "with freeboard"

1 D^K (Stl) & Shelter D^K (Stl)

CDB a & u E 152' f 180' 939t, FPT 77t, APT 124t.

FK, 6BH, (coll. BH. to Shelter d^K, 5 BH to 2nd d^K), com, Lloyd's A&C.P.

F 34'



Lloyd's Register Foundation

W41-0010

Statement No. _____ Date of Committee's Minute 28.02

IES IN SHIP.

3 1/2 3

3 3

3 1/2 x 3 1/2 x

3 1/4 x 5

5 5

5 5

4

2 x 5

3 1/2 4

5 4

times

plat

.40

7 x 4

1/2 x 4

.43

yes