

"  
m.v. Lagarto"

Broken Crankshaft

Micrographs

No 112 - From web near fracture.

No 111 From pin away from fracture.


No 115 From flange - after end.

— — — — —



No 112

x 80



No 111

x 80



No 115

←  
Direction of  
forging.