

Gross Tonnage
Register Tonnage

161.74

1st Longitudinal Number (L x D)

2271.5

Managers

W414-0034

F.E.

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *Slt. Sc. K "ARAB"*

Rpt. *Aut.* No. *44137*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.

Longl. ~~verse~~ No. *2271.5*

Depth "d" *✓*

Table No. *✓*

Description *Angle frames, as approved*

Longitudinal No. *6198.5*

Proportions Length *10.44*
Depth =

~~Deck~~ Sheerstrake *as approved*

This vessel appears to have been built in accordance with the plans and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.1 (Steel) "Steam Trawler"
1, 0k.
A P T_s 14t, F P T 9t
BK 8", 4 BH, Lem, Lloyds A + CP
Q. 85', F. 26'

24 10.33
alk

It is concluded the stiffening of the watertight bulkheads throughout is as approved but the Surveyors should state if this is so.

Poop Deck, Angle, E or C

