

1m.11.35.

1E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Spring wave

Rpt.

Std

No. 31961

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Triple Expansion

If Boilers fitted with forced draught

yes

Tail Shaft. If fitted with a continuous liner

yes

If fitted with an outside gland of

approved type

no

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + Line 11.36

Sgt.

Gmn

17.11.36

It would appear that the machinery for this vessel is a duplicate to that fitted to 5/8" Spring wood & 5/8" Spring wear. But the Surveyors should confirm this.

yes

279



© 2019

Lloyd's Register Foundation

W415-0106