

ARD REPORT on the

S.S. "El Oso"

It is submitted the Surveyor be informed that the depth of the hatch web indicated on back of Greenboard report for above vessel is given 8" whilst the depth shown on the approved plan in this Office is 11". It is presumed the depth of 8" is at the side of hatch and that the depth at centre is 11" but the surveyor should be asked to confirm this.



© 2019

Lloyd's Register
Foundation
W418-0055