

GENERAL REMARKS—(continued).

[Faint, mostly illegible handwritten notes in pencil and light blue ink, covering the upper half of the page. Some legible words include "ANCHOR", "STEEL", "WOOD", "BRIDGE", "TANKS", "MACHINERY".]

PARTICULARS FOR RECORD in the REGISTER BOOK.—Length of Poop ☒ ft., R.Q.D. 78 ft., Bridge ft., Forecastle 19.5 ft. (in feet and tenths). When the Poop is joined to the B.D., this should be distinctly stated.

No. and Material of Decks (if Iron or Steel) and whether wholly or partially covered with wood, and No. of tiers of Beams (this information is to be given should appear in the Register Book) 105.

Official No. ; Signal Letters . State if Machinery is fitted aft Mach aft.
How are the surfaces preserved from oxidation? Inside Paint, Cement, & Bituminastic Solution Outside Paint.

PARTICULARS OF WATER BALLAST.—State whether the Double bottom is constructed on the cellular system or with girders on floors.

Where Fitted.	*Length. Feet.	Water Capacity. Tons.	Where Fitted.	*Length. Feet.	Water Capacity. Tons.
Double bottom, aft,			Fore peak tank,		
Double bottom, under Engines and Boilers,			After peak tank,		
Double bottom, if under Engines only,			Deep tank, aft,		
Double bottom, if under Boilers only,			Deep tank, forward,		
Double bottom, forward,			Other tanks, if fitted,		
			(If necessary, furnish further information by sketch.)		
Total capacity of double bottom					

* The wells are not to be included in the lengths of the tanks.

State whether the above have been tested as required by the Rules. ☒

Order for Special Survey No. ☒

Date ☒

No. 887 in builder's yard.

DATES of Surveys held while building

1918: Sep 17, 20, 24, Oct 1, 4, 8, 11, 15, 22, 29, Nov 5, 19, 22, 29, Dec 5, 13, 17, 1919
Jan 7, Mar 5, 13, 18, 21, 26, April 9, 11, 15, 29, May 2, 6, 13, 30, June 6, July 17, 30
Aug 15, Sep 8

Surveyor's Signature

Matthew Blackwood

© 2018 38
Total No. of Visits

