

Tonnage opening fitted. Condition of class.

NAME OF VESSEL..."HARPAGUS".....

Extract from fresboard verification of marking form received from the ..Sunderland..... Surveyors dated the23/2/40.

Moulded depth	28	ft.	9	ins.
Corresponding draught	25	ft.	9 $\frac{1}{4}$	ins.
Moulded depth as shewn on draught sheet	28	ft.	9	ins.
Tropical freeboard	2	ft.	7 $\frac{3}{4}$	ins.
Summer	"	3	ft.	2 $\frac{1}{4}$ ins.
Winter	"	3	ft.	8 $\frac{3}{4}$ ins.
W.N.A.	"	-	ft.	-- ins.
Fresh Water allowance				6 $\frac{3}{4}$ ins.

Marked from ~~wood~~/steel upper deck.

Checked by.....

Date...30th April, 1940....



© 2020

Lloyd's Register Foundation

Solid Floors, thickness and spacing

Are Frame and Reversed Frame)

Bridge Deck, Angle, E or F