

2500, 12, 19.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "MANGALORE" Report Gls. No. 40,065.

For the CHIEF SHIP SURVEYOR ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24-7-92.)

Nature of Survey

When due


✱ 100 A-1. (steel)

2 Dks (steel) & 3<sup>rd</sup> Dk (steel) in N<sup>o</sup> 1 Hold.

Call DB 463' 2110 t. MT 35' 1490 t. DTA 40' 1568 t. FPT 111 t. APT 90 t.

FK. S BH. pk. cem. Lloyd's A.Y.C.P.

P49, B223, F42.



AEB.  
25-6-20

W432-0194

" " to Floors

br'dth & thickness (in way of Bridge)

20 32 32 20 6 x 6 .8 x 6



