

Lloyd's Register of Shipping

7m,8,34.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor *[Signature]*

VESSEL'S NAME

"MANGALORE"

Rpt. Mdb

No. 15385

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

The Middlesbrough Surveyors report this ship placed in dry dock, the bottom cleaned and coated, stream line plates welded to the rudder and similar plates fitted and electrically welded to the stern frame as approved.

The ship has been shortened 37'-6", ~~the midship deep tank and the deckhouses under bridge~~ dispensed with and alterations carried out to the Surveyors' satisfaction. (as per approved plans)

It is submitted the ship appears worthy to remain as classed with record of survey 4,35.

100A1

4,35 Mdb

Fitted for oil fuel etc.

R.B. Insert "Shortened 35"
Delete "MP 35' 1490t"
Amend "Cell DB 463' 2110t"
to "Cell DB 417' 1893t"



© 2005

Lloyd's Register Foundation
W432-0255

LONDON.