

the back of this form. State also the dates and initials of any letters respecting this case.
In damage cases where the Surveyor has not made a special damage report he is required to state whether he

5m,11,27.

24 FEB 1928

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME Stl.S.S. "KABINDA".

Rpt. Ant.

No. 15517.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Nature of Survey.....

The Antwerp Surveyors report this vessel placed in dry dock, the bottom cleaned and coated and damage through heavy weather and fire repaired as follows:- 2 shell plates and 4 deck plates renewed, 7 beams, 1 stringer plate and 5 deck plates repaired and minor repairs effected.

A bower anchor has been temporarily placed on board and it is stated this will be replaced by another anchor on vessel's return from the present voyage.

It is submitted the vessel appears worthy to remain as classed, with record of survey 2.28, subject to the equipment of anchors being placed in order on vessel's return from the present voyage, as recommended.

100A.1. } Subject to
2.28 ant }


23. 2. 28.



© 2019
Lloyd's Register
Foundation

FEB 14 JUN 1929

