

Depth

26.4

Draught Moulded

24-23/4

Yes

F.E.

Inspected by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl Se. Sr. WILLOMPOOL*Rpt. *Mdb.*No. *13356*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

*1st Long*Transverse No. *11313*Depth "d" *24.96*Framing: Table No. *273*Description *Channel frames as approved.*Longitudinal No. *33779*Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{13.56 \text{ to Upper dk.}}{}$ Deck Sheerstrake *As approved.*

This vessel appears to have been built in accordance with the *Revised* Rules and the approved plans, and it is submitted she is eligible to be classed

*100 A.1 (steel)**1 dk (stl)**Cell D.B. a 126' u E 25' f 171' 1103t F.P.T. 162t A.P.T 194t**F.K. 6B.H. Cem. Lloyds A & C.P.**P. 29' B. 221' F. 42'*© *2012*
*36.5.15*Lloyd's Register
Foundation

W436-0131

Spacing

24

27

