

of Main Boilers 350.
of Donkey Boilers one
Steam Pressure 180th
Main Boilers

Owners Pool Shipping Co. Ltd.
Managers

Owners' Address
(if not already recorded in the Register Book).
Port West Antlepool Voyage

Location (which
Register Book & ...)

4E

23 APR 1934

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

'S NAME

Willowpool

Rpt.

Hel

No.

17344

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

H.Cylinder renewed - 1/2 smaller in diameter & fitted with poppet valves.
I.Cylinder fitted with a liner 3" smaller in diameter.
Superheaters fitted.

It is submitted that
this vessel is eligible to
remain as CLASSED.

Book Amend H.Cylinder 8 25 1/2
" JP - " 40.

23/4/34



© 2019

Lloyd's Register
Foundation

W436-0142

Classed in the Register Book.

steam? 18
steam? ✓
? ✓
? ✓
? ✓
t the after en
ciently lubric
ter end of {
lubricated? }
and on
ng inde
wase
shanki
ed, sou
uitab
newed
b steam
aminea
aters ex
team as
Birkle
sequent upo
9, 11, B. & H.S.
contin