



S.S. "HARFRY" Hull Rpt. No. 34998...

It is submitted the Hull Surveyors be requested to state whether the screw shaft of this vessel, examined by them on ... 10/12/23, runs in oil and is fitted with an approved oil gland at its after end.

The Surveyors should be informed that in all future cases when reporting surveys on vessels whose screw shafts run in oil and are fitted with approved glands, or other approved appliances, the type of gland should be stated on the report.



© 2020 Lloyd's Register Foundation

Handwritten signature and date: 3/13/24

W443-0113