

COPY.

Lloyd's Register of Shipping.

Port DUNEDIN, N.Z.26th, May 1939.

This is to Certify that I have

Surveyed the S.S. "WAIKOUAITI", (3926 tons, G.R.), No. 86060 in Register, Owners, Union S.S. Co., N.Z. Ltd., afloat at Port Chalmers for Part Second Special Survey No. 3 for All Tanks Opened, Examined & Tested, All Holds, 'Tween Decks, Bunkers, Boiler & Machinery Spaces, Crew's Quarters, Weather Decks & Casings, Hatches, Ventilators, Openings, Masts & Rigging and Steering Gear.

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have Recommended that she be allowed to remain as classed in the Register, ∇ 100 Al., and the record of Survey (with date) and the Notation for 2nd, Special Survey No. 3 be made in the Register when the Survey has been completed.

being fit to carry a dry and perishable cargo.

To Complete the Survey, Vessel placed in Dry Dock, Shell Plating Examine and Drill Test, Rudder to Examine. Equipment to be examined, Anchors, Chain Cables to be ranged, Chain Locker to examine, Windlass to test.

Geo. W. Martin
Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."