

-7 MAY 1934

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "SINT ANNALAND" Rpt. Rot No. 22861a

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The Rotterdam Surveyors report this vessel placed in dry dock and the requirements of the 2nd S.S. No.1, due 7,33, complied with.

The bottom has been cleaned and coated, repairs effected to bulkheads, decks, bunker casings, after peak flat and minor repairs carried out.

It is submitted the vessel appears worthy to remain as classed with record of survey 4,34 and notation of S.S. No.1-34.

100A1

4,34 Rot

S.S. Rot No.1-34

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



© 2020

Lloyd's Register
Foundation

www.lloyd-reg.co.uk