

For the information of Surveyors and the Committee only.

Received at

Office

19

Lloyd's Register of Shipping.

Order: 6685/69074.

(Report on Vessel No.

7466

Port

TRIESTE

Duplicate.

M.V. Hilda

No. 3004

SHIP FORGINGS OR CASTINGS

I have to report that the undermentioned ~~ITALIA~~ Steel Forgings or ~~Castings~~ manufactured by Messrs. Dortmund Union of Dortmund for the Vessel No. 752, being built by Messrs. Atlas-Werke A.G. of Bremen have been inspected by me as set forth below and found to be, so far as can be seen, 1 rudder tiller sound and free from surface defects.-

on Forgings or Castings.

Lloyd's

No. 613.

L.H. 12.2.26.

Düsseldorf 13th February 1926.

for Mr. Karl Haupt

M. Herg

| | 1 rudder tiller | RUDDER FRAME. | STEM. |
|--------------------------|----------------------------------|---------------|-------|
| Material* | Annealed Siam. Mart. Ingot Steel | | |
| Made at | forged | | |
| Dimensions | | | |
| Process on Inspection | rough turned | | |
| When Inspected | 12.2.26. | | |
| CASTINGS. | .798 3" | | |
| on Standard Test Pieces. | | | |
| Test— | | | |
| per square inch | 31,4 | | |
| ension per cent. ... | 29,- | | |
| ending Test— | 180 degr. good | | |
| before fracture | | | |
| Test— | | | |
| at from ground ... | | | |
| ring Test— | | | |
| de according to Rules | | | |
| found satisfactory ... | | | |

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.


(if any chargeable) £

To be paid at Düsseldorf.

Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

is if annealed

yes.



© 2021

Lloyd's Register

W45-0076

77