

"WALMA"
=====

In reply to enquiry regarding the electrical installation fitted in this vessel, the Helsingfors Surveyor stated that the installation has not been examined.

It is submitted the Surveyor be informed that the installation should be examined in accordance with the Rules and particulars of the installation as requested on the attached endorsement dated 18.8.39 should be forwarded to this Office at the earliest opportunity.

Mu

222.8.39



© 2019

Lloyd's Register
Foundation

W451-0104