





Form No. 1B. WEB FRAMES, FORGINGS OR CASTINGS, BULKHEADS, PLATING, RIVETING, FRAMES, REVERSED FRAMES, MASTS, SPARS, &c. Includes sections for keel, stem, stern-post, rudder, bulkheads, plating, riveting, frames, reversed frames, masts, spars, &c.

EQUIPMENT No. 37537 LETTER Z ANCHORS. Includes sections for anchors, chain cables, hawsers and warps, steering gear, pumps, windlass, engine room skylights, coal bunker openings, cargo hatchways, web plates, shifting beams and fore and afters to each hatch, butts, height above deck and description, correspondence, workmanship, and general remarks.

W454-0009 (2/2)



GENERAL REMARKS—(continued).

**PARTICULARS FOR RECORD in the REGISTER BOOK.**—Length of Poop ☒ ft., R.Q.D. ☒ ft., Bridge ☒ ft., Forecastle ☒ ft. (in feet and tenths). When the Poop is joined to the B.D., this should be distinctly stated ☒

No. and Material of Decks (if Iron or Steel) and whether wholly or partially covered with wood, and No. of tiers of Beams (this information is to be given should appear in the Register Book) *ONE DECK PL. AND SHELTER DECK PL. 2 TYS 8 IN.*

Official No. ☒ ; Signal Letters ☒ State if Machinery is fitted aft

How are the surfaces preserved from oxidation? Inside *PORTLAND CEMENT AND PAINT* Outside *PAINT*

**PARTICULARS OF WATER BALLAST.**—State whether the Double bottom is constructed on the cellular system *or with girders on floors* ☒

Where Fitted.	*Length. Feet.	Water Capacity. Tons.	Where Fitted.	*Length. Feet.	Water Capacity. Tons.
Double bottom, aft,	<i>132.16</i>	<i>362</i>	Fore peak tank,	-	<i>105</i>
Double bottom, under Engines and Boilers,	<i>21.67</i>	-	After peak tank,	-	<i>231</i>
Double bottom, if under Engines only,	<i>21.67</i>	<i>92</i>	Deep tank, aft,	-	-
Double bottom, if under Boilers only,	<i>19.50</i>	<i>80</i>	Deep tank, forward,	<i>15.16</i>	<i>606</i>
Double bottom, forward,	<i>186.33</i>	<i>626</i>	Other tanks, if fitted,	-	-
Total capacity of double bottom		<i>1160</i>	(If necessary, furnish further information by sketch.)		

\* The wells are not to be included in the lengths of the tanks. *359.16*

State whether the above have been tested as required by the Rules ☒

Order for Special Survey No. *5458*

Date *24.12.19*

No. *551* in builder's yard.

DATES OF SURVEYS  
held while building

*1920. May 27, June 8, 16, July 1, 5, 6, 22, 28, 30, Aug. 10, 16, 19, 30, Sep. 16, 22, Oct. 1, 7, 8, 11, 12, 13, 14, 18, 29, Nov. 1, 5, 8, 15, 18, 24, 26, 29, Dec. 2, 3, 7, 9, 14, 19, 21, Jan. 21, Dec. 30, 1922, Jan. 5, 6, 10, 11, 12, 20, 24, 30, Feb. 2, 3, 6, 7, 8, 9, 13, 16, 20, 21, 23, 27, 28, March 1, 2, 3, 6, 7, 8, 13.*

Surveyor's Signature

*L. S. [Signature]*

© 2020

Total No. of Visits *71*

Lloyd's Register  
Foundation