

Condition of Class

NAME OF VESSEL... MUNSTER

Extract from Freeboard Verification of marking form received
from the..... BELFAST Surveyors dated the 2.3.3.8.

Moulded depth 19 ft. 0 ins.

Corresponding draught 15 ft. $1\frac{1}{4}$ ins.

Moulded depth as shown
on draught sheet. 19 ft. 0 ins.

Tropical freeboard - ft. - ins.

Summer " 3 ft. $11\frac{3}{4}$ ins.

Winter " 4 ft. $3\frac{1}{2}$ ins.

" " - ft. - ins.

Fresh Water Allowance $3\frac{3}{4}$ ins.

Marked from ~~xxxx~~/steel upper deck.

Checked by..... *DM*
Date..... 10 MAR 1938



© 2020

Lloyd's Register
Foundation

W456-00 85