

W 457 -0175

to Chief Surveyors

Received from Chief Surveyors

SEL'S NAME *Stet S-S "LANGFJORD"*

Report

90

No. *41522*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

ure of Survey

When due

Separate endorsement regarding date of build


** 100-A-1. (Stil) "Shelter Deck with foreboard" ✓*

1 Dk (Stil) & Shelter Dk (Stil) ✓

Cell DB 174' 240t, FPT 49t, APT 26t ✓

FK, Collision BH to Shelter Dk, 3 BH to upper Dk, Cen, Planks A. & C. F 34' in Shelter Dk ✓

Date of build 12, 21 ✓



© 2020

Lloyd's Register
Foundation

2-1-22