

2WB 172 SEC 4^A

1m.11.36.

fees paid

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel Screw M.S. "SAN CALISTO" Report Grk. No. 20318

For the CHIEF SHIP SURVEYOR ~~XXXXXXXXXXXXXXXXXXXXXXXXXXXX~~

(In cases which have to be submitted to the Cladding Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Cladding Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First Entry When due --

*100Al 'Carrying Petroleum in bulk'

1 Dk. 2nd Dk. clear of cargo tanks, 'Longitudinal Framing at bottom and at deck'

Cell. DBuE 66' 16lt, DTf 22' 21st, FPT 149t, APT 96t.

FK, 15 BH, pt. Cem., Lloyd's A & CP.

P. 97', B 46' F 48'.

Machy. aft.

OVERALL LENGTH = 478'6 ✓



© 2020

Lloyd's Register Foundation

Handwritten signatures and dates: 4.3.37

W463-0057

Floors, Depth and thickness at mid-line in }
Holds

in Walls, Angle, E or F }
in way of Bridge, Angle, E or F }