

Rpt. C 12(a).

# FREEBOARD VERIFICATION FORM FOR ORDINARY CARGO AND/OR PASSENGER SHIPS.

When received in London Office.....

Port Cardiff

Name S.S. Sea Rambler

Official No. 149165 No. in Reg. Book

Port of Registry (For Foreign Ships) Dover

Iron or Steel \_\_\_\_\_ State whether Classed by Lloyd's Register +100A.1

Name of Owners \_\_\_\_\_ Date of Verification \_\_\_\_\_

I have to report that the Freeboards as given below, assigned by the Committee to this ship, have been correctly marked on the ship's sides, in accordance with the printed instructions:—

	FREEBOARD AMIDSHIPS FROM TOP OF DECK LINE, <del>WOODEN</del> /STEEL DECK.	FROM CENTRE OF DISC.
Tropical Fresh Water . . . . .	2 ft. 4 1/4 ins.	8 ins. above
Fresh Water . . . . .	2 ft. 7 1/4 ins.	5 ins. above
Tropical . . . . .	2 ft. 9 1/4 ins.	3 ins. above
Summer . . . . .	3 ft. 0 1/4 ins.	
Winter . . . . .	3 ft. 3 1/4 ins.	3 ins. below
Winter North Atlantic . . . . .	3 ft. 5 1/4 ins.	5 ins. below

Maximum Summer Draught corresponding to the freeboard assigned as shown on the Builders' Displacement Scales:—

Surveyor.

(To be filled up in London Office.)

Statement No. 33621 Date of Committee's Minute \_\_\_\_\_

Particulars for Record in Register Book.	{	Moulded Depth . . . . .	ft.	ins.
		Freeboard . . . . .	ft.	ins.
		Corresponding Draught . . . . .	ft.	ins.

Freeboards compared and found correct by \_\_\_\_\_ Date © 2020

Is fee paid? \_\_\_\_\_ Form for Certificate L.L.2 - 31/8/1935

Instructions \_\_\_\_\_ Date \_\_\_\_\_

Certificate written 5.10.35 Noted for posting \_\_\_\_\_