









GENERAL REMARKS—(continued).

*[Faint, mostly illegible handwritten text in the upper section of the form, likely containing general remarks and survey details.]*

PARTICULARS FOR RECORD in the REGISTER BOOK.—Length of Poop ft., R.Q.D./85 7 ft., Bridge 63 ft., Forecastle 32 ft.  
(in feet and tenths). When the Poop is joined to the B.D., this should be distinctly stated

No. and Material of Decks (if Iron or Steel) and whether wholly or partially covered with wood, and No. of tiers of Beams (this information is to be given as it should appear in the Register Book) One deck Steel  
Official No. 140680 ; Signal Letters \_\_\_\_\_ State if Machinery is fitted aft No  
How are the surfaces preserved from oxidation? Inside Paint & Cement Outside Paint

PARTICULARS OF WATER BALLAST.—State whether the Double bottom is constructed on the cellular system or with girders on floors.

Where Fitted.	*Length.		Where Fitted.	*Length.	
	Feet.	Tons.		Feet.	Tons.
Double bottom, aft,	<u>94.48</u>	<u>260</u>	Fore peak tank,	<u>25.04</u>	<u>130</u>
Double bottom, under Engines and Boilers,	<u>40.50</u>	<u>140</u>	After peak tank,	<u>18.00</u>	<u>151</u>
Double bottom, if under Engines only,			Deep tank, aft,		
Double bottom, if under Boilers only,			Deep tank, forward,		
Double bottom, forward,	<u>128.25</u>	<u>295</u>	Other tanks, if fitted,		
	Total capacity of double bottom	<u>695</u>	(If necessary, furnish further information by sketch.)		

\* The wells are not to be included in the lengths of the tanks.

State whether the above have been tested as required by the Rules Yes

Order for Special Survey No. 4647

Date 12.9.1916

No. 204 in builder's yard.

DATES OF SURVEYS held while building

1916  
May. 15. 29. Jun. 7. Jul. 18. 28 Aug. 11. Sep. 6. 15. 26. Oct. 5. 19. Nov. 6. 13. 16  
21. 29. Dec. 5. 8. 14. Jan. 4. 10. 17. 24. 31. Feb. 8. 15. 26. Mar. 9. 12. 16. 27. Apr. 18. 26  
May. 4. 7. 8. 9. 22. Jun. 5. Jul. 9. 24. 28. 30. 31.

Total No. of Visits 44

Surveyor's Signature