

FREEBOARD VERIFICATION FORM FOR STEAMERS.

When received in London Office

TUE APR. 3 1923

Port

Bilbao

Vessel's Name

S.S. "Cabo Cullera"

Official No.

✓

No. in Reg. Book

55539

Port of Registry (For Foreign Vessels)

Sevilla (Spanish)

Iron or Steel

Iron

State whether Classed by Lloyd's Register

yes.

Name of Owners

Ybarra & Co.

Date of Verification

27th March 1923.

30711

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line . . . ft. . . ins.

From centre of disc to top of statutory deck line } *9'* ft. *8 1/2"* ins.
at awning or part-awning deck . . . }Fresh Water line above centre of disc . . . *5"* ins.Indian Summer line above centre of disc . . . *✓* ins.Winter line below centre of disc . . . *5 1/2"* ins.Winter North Atlantic line below centre of disc . . . *✓* ins.Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or steel deck with the vessel's side } at main, spar or upper dk. *✓* ins.
at awning or pt. awning dk. *1 1/2 wood 7 1/2* ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or steel deck.

The three freeboard certificates have been handed to the owners

J. de Berazá Surveyor.

(To be filled up in London Office.)

Statement No. *1110*

Date of Committee's Minute

26.4.06

Particulars for record in Register Book.

Moulded Depth . . . *28* ft. *5* ins.Freeboard . . . *9* ft. *8 1/2* ins.Corresponding Draught . . . *19* ft. *10* ins.

Freeboards compared and found correct by

*W.D.*Date *3.4.23*

Is fee paid?

Form for Certificate

Instructions

Date

Certificate written *Already written* Noted for posting

2019
Lloyd's Register
Foundation