

FREEBOARD VERIFICATION FORM FOR ORDINARY CARGO ^{AND}_{OR} PASSENGER SHIPS.

When received in London Office

Port BilbaoName CantabriaOfficial No. _____ Signal Letters E.A.A.L No. in Reg. Book 70211Port of Registry Santander Gross Tonnage 5649

Class _____ Date of Verification _____

Name of Owners _____

I have to report that the Freeboards as given below, assigned by the Committee to this ship, have been correctly marked on the ship's sides, in accordance with the printed instructions:—

| | FREEBOARD AMIDSHIPS FROM TOP OF DECK LINE, | | FROM CENTRE OF | |
|----------------------------------|--|--------------------|----------------|------------------|
| | Wood /STEEL | <u>upper</u> DECK. | DISC. | |
| Tropical Fresh Water | 1447 | 56.97 ins. | 321 | 12.64 ins. above |
| Fresh Water | 1599 | 62.96 ins. | 169 | 6.65 ins. above |
| Tropical | 1616 | 63.62 ins. | 152 | 5.99 ins. above |
| Summer | 1768 | 69.61 ins. | | |
| Winter | 1920 | 75.60 ins. | 152 | 5.99 ins. below |
| Winter North Atlantic | ✓ | ins. | ✓ | ins. below |

Maximum Summer Draught corresponding to the freeboard assigned as shown on the Builders' Displacement Scales:—

Surveyor.

(To be filled up in London Office.)

Minutes of Committee's Minute

| | | | |
|--|-----------------------|-----|------|
| Particulars for Record in Register Book. | Moulded Depth | ft. | ins. |
| | Freeboard | ft. | ins. |
| | Corresponding Draught | ft. | ins. |

Freeboards compared and found correct by

Date

Form for Certificate

Certificate written

Noted for posting

© 2020

Lloyd's Register Foundation

W471-0043