

COPY.

Lloyd's Register of Shipping.



Port BAHIA BLANCA

2nd APRIL 1935

This is to Certify that

D. C. BRUCE

the undersigned Surveyor to this Society did at the request of Captain J.W.PATERAS survey, on the 2nd April, his vessel the :

S.S. "OINOUSSIOS"

3716 tons net register of CHIOS whilst afloat and at her loading berth at PUERTO GALVAN for repairs and also the adjusting, under steam pressure, of the boiler safety valves.

- (1) On examination the undersigned found that :
- the steel plate bracket carrying the port side steering chain guide pulley in way of the engine room, which on a previous voyage had been carried away and temporarily repaired by bolting same to deck, now satisfactorily riveted to the deck.
- (2) The undersigned adjusted, under steam pressure the safety valves of the port, centre and starboard boilers to blow off at a pressure of 180 pounds per sq. inch.-

DC Bruce

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for accuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."