

# Lloyd's Register of Shipping. RPT. No 4912.

JUL 26 1939

## REPORT ON ANNUAL LOAD LINE SURVEY.

Name of Ship INVERDARGLE Official Number 159815 Port of Registry DUBLIN  
 Place of Survey PIRAEUS Date of Survey 19th JULY 1939 Date of last Load Line Survey 21/7/38 Date of Issue

### PARTICULARS OF SURVEY.

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
<b>HATCHWAYS, INCLUDING SMALL HATCHWAYS.</b> (OIL TIGHT COVERS TO OIL TANKS)			
<b>1. Exposed on freeboard deck.</b>			
Coamings, their stays and stiffeners...	Good ✓		
Beams ...	Good ✓		
Fore and afters ...	✓		
*Covers ...	Good ✓		
*Tarpaulins ... (State number per hatchway)	✓		
*Cleats and battens ...	✓		
Lashings and their fittings ...	✓		
Wedges ... (Is supply, including spares, adequate?)	✓		
<b>2. Exposed on superstructure decks, including raised quarter decks.</b>			
HATCHWAY TO FOREPEAK ON FORE DECK " TO CARGO HOLD ON " } ALL HAVE STEEL COVERS " TO CREWS QUARTERS ON POOP DECK	Good ✓		
Coamings, their stays and stiffeners ...	Good ✓		
Beams ...	✓		
Fore and afters ...	✓		
*Covers ...	Good ✓		
*Tarpaulins ... (State number per hatchway)	✓		
*Cleats and battens ...	✓		
Lashings and their fittings ...	✓		
Wedges ... (Is supply, including spares, adequate?)	✓		
<b>3. Within superstructures not intact or not protected by Class I closing appliances.</b>			
Coamings ...			
Beams ...			
Fore and afters ...			
Covers ...	✓		
Tarpaulins ... (State number per hatchway)			
Cleats and Battens ...			
Wedges ... (Is supply, including spares, adequate?)			

RETAIN

RETAIN



© 2020  
Lloyd's Register  
Foundation

\*Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Board of Trade Circular 1687, paragraph 117 (i)).

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
<b>VENTILATORS IN EXPOSED POSITIONS.</b>			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections	Good ✓		
Closing arrangements	Good ✓		
	Good ✓		
5. To spaces below decks of superstructures which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections	Good ✓		
Closing arrangements	Good ✓		
<b>AIR PIPES.</b>			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements	Good ✓		
	Good ✓		
7. Within partially enclosed superstructures.			
Closing arrangements	✓		
<b>MACHINERY CASINGS.</b>			
8. Casing Top.			
Fiddle openings, their covers and fastenings	Good ✓		
Skylights, their fastenings, covers and lashings	Good ✓		
	Good ✓		
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings	✓		
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings	Good ✓		
	Good ✓		
11. Within partially enclosed superstructures.			
Doors and fastenings	✓		
12. FLUSH BUNKER SCUTTLES and chain attachments			
	✓		
13. COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings, covers	Good ✓		
	Good ✓		

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
<b>14. CLOSING APPLIANCES FOR OPENINGS IN SUPERSTRUCTURE BULKHEADS.</b>			
Forecastle	Good ✓		
Bridge, fore end...	No openings ✓		
Bridge, after end	Good ✓		
Poop	Good ✓		
<b>15. GANGWAY, CARGO AND COALING PORTS.</b>			
In ship's side and superstructures	✓		
<b>16. SCUPPERS AND SANITARY DISCHARGE PIPES.</b>			
Valves	Good ✓		
<b>17. SIDE SCUTTLES AND DEADLIGHTS</b>			
	Good ✓		
<b>18. GUARD RAILS</b>			
	Good ✓		
<b>19. PROTECTION AND ACCESS TO CREW'S QUARTERS.</b>			
Gangways	Good ✓		
<b>20. LIFELINES (fittings and material)</b>			
	✓		
<b>21. FREEING PORTS</b>			
Shutters	✓		
Protection bars			
<b>22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.</b>			
Fittings or appliances	Good ✓		
<b>23. ITEMS NOT INCLUDED IN THE FOREGOING</b>			
	✓		
<b>24. LOAD LINE MARKS</b>			
	Verified & found correct ✓		

RETAIN



Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11.

IN CLOSING APPLIANCE FOR OPENINGS IN SUPERSTRUCTURE BULKHEADS

IN CLOSING APPLIANCE FOR OPENINGS IN SUPERSTRUCTURE BULKHEADS

IN CLOSING APPLIANCE FOR OPENINGS IN SUPERSTRUCTURE BULKHEADS

**Certificate A. To be signed by Surveyor in respect of a partial or complete survey.**

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Board of Trade Circular 1687, and the requisite details of the survey have been entered herein.

Index Nos. of items examined. †	Signature of Surveyor.	Place.	Date.
<i>all</i>	<i>P. V. Balfout</i>	<i>Pitcairn</i>	<i>19th July: 1939</i>

**Certificate B. To be signed by Surveyor completing the survey.**

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor *P. V. Balfout.* Place *Pitcairn* Date *19th July: 1939*

Signature *P. V. Balfout* ✓  
Date *19th July: 1939*

† Insert "all" in case of a complete survey.

*82*  
*20/7/39*

Fee £ 6.0.0. TRAV. EXPENSES 10/- ✓

Number of Visits 1

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a certified copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.



© 2020

Lloyd's Register Foundation