

REPORT of SURVEY for REPAIRS &c.

REPORT OF TOTAL LOSS, CASUALTY, &c. 9046

No. 23129 in R. B. Wreck Book, p. 121/35

Date of writing this report 18th December, 1935

Vessel's Name Steel S.S. "Boimbra"

of Lisbon

Tons { Net 2989
Gross 4915

Built at Greenock When 1916 4 Casualty notice sent to Owner

Owner's reply

Owner's Name Empresa de Nav. Luso-Marroquina, Ltda

Address Praça Luis de Camões 22-2º, Ato, Lisbon.

SOURCE OF INFORMATION.

previously before Date
Committee. Last Minute

Particulars of Classification.
+ 100A1 + LMC
7.35 MS 11.32
S.S. No 3-2.28 BS 1.35
S.S. No 1-32 TS 6.35 CL
Carrying Petroleum in bulk
Fitted for oil fuel 2.23 F.P.
above 150°F.

Casualty

particulars of Casualty In July last the Bilbao

Surveyors reported this vessel placed in dry dock, and among other items some patches were fitted in Nos. 3, 5 & 7 tanks, and in the summer tanks. After completion of the work the tanks were tested and found satisfactory.

In a letter dated the 11th instant the Lisbon Surveyor states he has been informed officially by the Owners' Superintendents (Vacuum Oil Company) in New York, that the vessel has been condemned and will be broken up, as the repairs carried out at Bilbao have not remedied the defects in the cargo space, which is in a bad condition.

Suggested Record

To be broken up

Date of Committee

Tue. 17th Dec. 1935

Committee's Minute

(See Minute on Bilbao Report No. 8635)