

Les.  
Les.  
7

om.2.16.

1

Wandsworth Works

RECEIVED

Sent to Chief Surveyors 8.4.16

Received from Chief Surveyors

VESSEL'S NAME *Sheela Venmchar*

Report *Erk*

No. 16986

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey . . . . . When due . . . . .

\* 100 A-1. (Steel) Laming petiole in hull  
2 Drs (Steel) & Webframes. Longitudinal Framing.  
CU DB w. E & B 8' 204L . FPT 110 . APT 95L  
FK. 16 BH. 15 BH & UD 1 BH & 2 Dr. Lloyd's rep. pt. can.  
P 106. B 35. F 52. Archy apt.

*M*  
10.4.16



© 2019

Lloyd's Register  
Foundation