



Lloyd's Register of Shipping.

Collingwood Buildings, Newcastle-on-Tyne.

23/6/21.

Reference

Dear Sir,

30/6

In view of the fact that the German vessel *"Hannes"* is now undergoing survey, in order that she may be cleared with this Society, I am forwarding the following particulars, for the information of the Committee :-

Diam: of Cylinders :- $24\frac{3}{16}$ ", $34\frac{3}{4}$ ", $50\frac{9}{16}$ " - 73"

Stroke of piston :- $53\frac{1}{8}$ "

Screw shaft fitted with a continuous liner? - Yes!

Dia: of crank shaft journals :- $14\frac{1}{16}$ "

" " " " pins :- $14\frac{15}{16}$ "

Size of crank webs :- $22\frac{3}{16}$ " x $9\frac{13}{16}$ "

Dia of thrust shaft under collar :- $14\frac{3}{4}$ "



Lloyd's Register
Foundation

W48-0200 (1/2)

dia: of intermediate shafting :- 14"

" " screw shaft :- 15 $\frac{7}{8}$ "

The owners have been in communication with builders,
but have been unable to secure a plan of the boiler, or the
eng: room pipe arrangement.

A plan of the pumping arrangements will be forwarded
in the course of a few days.

I am, Dear Sir

Yours faithfully

C. W. Stuart



© 2020

Lloyd's Register
Foundation

W48-0200 (2/2)

Referred to the Chief ~~Ship~~ Surveyor,
and the Chief Engineer Surveyor.

CRD
4 JUN 1924

Referred to Mr. *Mayne*.



© 2020

Lloyd's Register
Foundation