

For the information of Surveyors and the Committee only.

Received at _____ Office _____ 19

Lloyd's Register of Shipping.

(Report on Vessel No. 20880 Port Rot)

No. 3757 SHIP ~~FORGINGS~~ OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings~~ or Castings, manufactured by Nederlandsche Staalfabrieken of Utrecht for the Vessel ~~No.~~ "Elsa Menzell", being built up by Messrs. Wilson of _____ have been inspected by me as set forth below and found to be, so far as can be seen, free from defects.

Mark on Forgings or Castings.

Lloyd's
Nos. 851 & 852
H.P.B. 11-1-32 & 14-1-32.

Port of AMSTERDAM, 19th December, 1932.

[Signature]


	One Sole piece	STERN FRAME.	BUDDEBO FRAME.	SKM.
Material*	...	S.M. Steel	One Connecting plate S.M. Steel	
How made	...	Cast	Cast	
annealed	...	Yes	Yes	
Dimensions	...	As per plan	As per plan	
Progress on Inspection	...	Rough cast	Rough cast	
When Inspected	...	8, 11 & 14 Jan.	8, 11 & 14 January, 1932.	
CASTINGS.				
Tests on Standard Test Pieces.				
Compressive Test—				
Tons per square inch	...	30.8	30.5	
Extension per cent.	32	34	
Bending Test—				
Angle before fracture	...	Good	Good	
Impact Test—				
Height from ground	-	-	
Hardening Test—				
If made according to Rules and found satisfactory	Good	Good	

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) EX : :

To be paid at Amsterdam.

If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.



© 2019

Lloyd's Register
Foundation
W481-0070