

# Lloyd's Register of Shipping.

(Report on Vessel No. 20880

Port

Rot

No.

## SHIP FORGINGS ~~OR CASTINGS~~

I have to report that the undermentioned ~~Steel Forgings~~ ~~Castings~~, manufactured by ~~Simon N.V. Wilson's Engineering & Shipway Co~~ of ~~Rotterdam~~ <sup>ELSA HANJELL, repaired</sup> for the Vessel ~~No.~~ being built by ~~N.V. Wilson's Engineering & Shipway Co~~ of ~~Schiedam~~ have been inspected by me as set forth below and found to be, so far as can be seen, free from defects.

Forgings or Castings.

Lloyd's

No. 189

1.10-1-32.

Rotterdam 18-1-32.

*J. H. Schmeijer*


	RUDDER POST OF STERN FRAME.	RUDDER <sup>head and</sup> FRAME. <sub>main piece</sub>	STEM.
...	<i>Siemens Martin Steel</i>	<i>Siemens Martin Steel</i>	
...	<i>Forged</i>	<i>Forged</i>	
...	<i>yes</i>	<i>yes</i>	
...	<i>as per old one</i>	<i>as per old one</i>	
on Inspection ...	<i>Forged and machined</i>	<i>Forged and machined</i>	
n Inspected	<i>10-1-32.</i>	<i>10-1-32.</i>	
STINGS.			
Standard Test Pieces.			
est—			
square inch	<i>31.2 Tons</i>	<i>31.2 Tons</i>	
per cent. ...	<i>34 %</i>	<i>34 %</i>	
ing Test—			
ore fracture	<i>100° good.</i>	<i>100° good.</i>	
om ground ...			
g Test—			
according to Rules			
nd satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

f any chargeable) £

be paid at

n, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.



© 2019

Lloyd's Register Foundation

W482-0021