

# Lloyd's Register of Shipping.

(Report on Vessel No. \_\_\_\_\_)

Port \_\_\_\_\_

No. 5280

## SHIP ~~FORGINGS~~ OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or~~  
Castings, manufactured by Messrs Gammell Laird & Co.  
of Sheffield for the Vessel No. 14, being built  
by The Kinghorn Shipbuilding Co. of Kinghorn  
have been inspected by me as set forth below and found to be, so far as can  
be seen, Satisfactory

S.S. "Kinghorn"

Mark on Forgings or Castings.

Lloyd's

No. 2131

W.G.H.  
23.4.20

W.G.Hume

Sheffield 25/5/20

	STERN FRAME.	RUDDER FRAME.	1 STEM.
Material*			Swiss Steel
How made			Cast
Dimensions			Finished
Progress on Inspection			3/13/19 - 23/4/20
Date when Inspected			
CASTINGS.			
Tests on Standard Test Pieces.			
Tensile Test—			7340 Middle 319
Tons per square inch			230 260
Extension per cent.			120° 120
Cold Bending Test—			
Angle before fracture			8 feet
Drop Test—			Satisfactory
Height from ground			
Hammering Test—			
If made according to Rules and found satisfactory			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £ ✓

To be paid at

\* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.