

yors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

E. *M. S.* "ELSA MENZELL" Report *N. J. H.* No. *32730*

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

*Damage*

When due \_\_\_\_\_

*Subject to vessel being further examined at a home port for ice damage.*

*[Signature]*

*NMB*  
*21.4.31.*

*other condition.*



© 2019

Lloyd's Register  
Foundation