

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME *Stat S.S. "AMALTHUS"*Report *S/o*No. *3629***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey _____

When due _____

* 100-A-1. (Steel) Carrying petroleum in bulk
 2 Dks (Steel) + Webframes, Longitudinal framing
 Cell DPB v E. B 81' 230t, DH 32' 328t, FPT 86t, APT 89t
 FK, 15 BH (11 to upper Dk, 4 to 2nd Dk), At asp, A. P.

P110' B33' F57' Webby Off

SO. 2/12/21
 This being a Sister vessel to the S.S. "AMPULLARIA" it is concluded the Longitudinal
 framing etc is as required but the Surveyors should be requested to forward
 particulars of same on Rpt 1* as these do not appear to have been received
See also 25-12-21
23-11-21

W485-0229