

1

Sent to Chief Surveyors 18. 11. 14

Received from Chief Surveyors

VESSEL'S NAME

Steelso Mahanada

Report

Lo

No. 34565

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st Entry.

When due

✱100A1. (Steel)

2 Dks (Steel) + 3rd Dk (Steel) in Hot Hold.

WB = Case DB at 158' x 1376' + 178' 1563L, FPT 796, APT 54L.

FK. 7BH. Cam, Lloyd av. P46, B124, F43

M
19. 11. 14



© 2020

Lloyd's Register
Foundation

W49-0123